

California Regional Water Quality Control Board Central Valley Region

Karl E. Longley, ScD, P.E., Chair



11020 Sun Center Drive #200, Rancho Cordova, California 95670-6114
Phone (916) 464-3291 • FAX (916) 464-4645
http://www.waterboards.ca.gov/centralvalley

28 August 2008

CERTIFIED MAIL 7006 0810 0002 9651 0070

Eric Mische Freeport Regional Water Authority 2710 Gateway Oaks Drive, Suite 320S Sacramento, CA 95833

NOTICE OF VIOLATION, CWA SECTION 401 WATER QUALITY CERTIFICATION, FREEPORT REGIONAL WATER PROJECT, WDID# 5B39CR00109, SACRAMENTO AND SAN JOAQUIN COUNTY

On 19 August 2008, Water Board staff inspected the Folsom South Canal Connection of your project. During the inspection, staff observed that grading had occurred within the creek channel of Dry Creek at a crossing on Clay Station Road in Sacramento County. Water Board staff noted that appropriate Best Management Practices had not been installed prior to entering the creek channel and that the area was not protected from washout and erosion. Water Board staff also noted that earthen material from the excavation work at the Dry Creek Crossing has been placed in the surface water drainage course and could pass into surface waters. Staff determined that this is a violation of the following conditions of your CWA Section 401 Water Quality Certification:

Additional condition 2 of your Water Quality Certification states, "Except for activities permitted by the U.S. Army Corps under §404 of the Clean Water Act, soil, silt, or other organic materials shall not be placed where such materials could pass into surface water or surface water drainage courses." Additional Condition 7 requires that, "All areas disturbed by project activities shall be protected from washout and erosion."

Your project must also meet the requirements of the Construction Storm Water General Permit. The General Permit requires you to meet the Best Available Technology economically achievable (BAT) and Best Conventional Pollutant Control Technology (BCT) standard to reduce or eliminate pollutant discharges from your site. Sediment is a pollutant.

During the 19 August 2008 inspection, Water Board staff observed tracking on the roadway in many areas along the pipeline project and inadequate and unmaintained construction entrances. Staff also observed that a rotary sweeper was being used to sweep the roadway and that the rotary sweeper was causing significant dust issues and was inadequate at cleaning the roadway. Rotary sweepers move the dirt to the side of the road where sediment can find its way into drainage courses. The BMPs currently employed to address sediment in the roadway at this site must be upgraded to meet the BAT/BCT standard.

California Environmental Protection Agency



Response

In response to this Notice of Violation, you must immediately do the following:

- Install appropriate BMPs at the Dry Creek Crossing prior to continuing excavation activities. Ensure that all other crossings have appropriate BMPs installed.
- Address the tracking on the roadway throughout the Folsom South Canal Connection portion of the project; this includes the installation and maintenance of appropriate construction entrances as needed.
- Review and update the Storm Water Pollution Prevention Plans for Folsom South Canal Connection to ensure that adequate BMPs are used for this phase of the project as well as providing an implementation schedule for the upcoming wet weather season.
- Provide a copy of all Storm Water Pollution Prevention Plans for the Folsom South Canal Connection portion of the project to our office.

Violations of your CWA Section 401 Water Quality Certification have exposed Freeport Regional Water Authority to possible further enforcement action. Under Section 13385 of the CWC, the Regional Board can impose administrative civil liabilities for violations of any water quality certifications issued pursuant to CWC Section 13160. The maximum administrative civil liability for each day of violation is ten thousand dollars (\$10,000).

If you have any questions, please contact Jacque Kelley at (916) 464-4764 or Rich Muhl at (916) 464-4749.

Sue Y. McConnell

Chief, Storm Water Compliance and Enforcement Unit

Enclosures: Inspection report

Site photographs

cc: Phillip Kohne, East Bay Municipal Utility District, Clements
Robin Cort, Freeport Regional Water Authority, Sacramento
Kerry Schmitz, Sacramento County Department of Water Resources, Sacramento
Archie Wright, Sacramento County Department of Water Resources, Sacramento

Storm Water Construction General Permit & 401 WQ Cert. Inspection Report

Signature

KWQCB - Region 33									
WDID # 5839CR00109 & various Cons	. Rermit#	s.	County: Sacramento & San Jeaquin Co.						
Owner's Name 2740 Gateway Oaks Drive, Suite 320 S Owner's Street Address Sacramento, CA 95833 Owner's City, State and Zip code Robin Cort & Phillip Kohne Owner's contact person and phone # Jacque Kelley, Rich Muhl Inspection Conducted By Dr X Hox Clear Overcast Cold Raining Weather Conditions During Inspection (circle all that apply)			Preciport Regional Water Project						
			Contact Pipeline project Site Address Sacramento & San Joaquin Co Site City, State, and Zip Code 8/19/2008 Date of Inspection In progress Status of Construction						
					Type of Inspection: Inspection in Termination Compliance Outreach Inspection in Termination in Termination Outreach Inspection in Termination	Request Inspection spection Facility Req o previous in	uest	* Date of Previous Inspection	
								Control Measures Checklist:	
					Storm Water Samples Collected?	Yes	No	Yes - Evident on inspection No - Non evident on inspection Areas of Concern: Yes N	-
Non-Storm Water Discharge or Evidence	*#W#\$\$D		Evidence of erosion?	ea.					
of Non-Storm Water Discharge Observed?	Yes	No	(hills, gullies, slips) Dirt/sediment tracked in streets?						
Separate Inspection Report Written?	Yes	No	Evidence of dewatering?						
Updated SWPPP on Site?			Other State of the Control of the Co						
	Yes	No							
Inspection Summary (complete only if no sepa									
Folsom South Canal Connection project ar	easi staff	observed a	king on the roadway. During the inspection of the a 401 Cert violation at the Dry Creek Crossing.						
			o noted inadequate and unmaintained BMPs for tracki s to review, update and implement, the SWPPP and	ng					
			ssociated w/project are 5S39C347805; 5S39C350311	•					
and the second s	a New York								
1/11			Date Entered:						
VI QUELLE			Entered By:						
Signature			Senior Review: SNM						



Figure 1: Overview of the Dry Creek Crossing



Figure 3: Area where the creek has been pot holed




Figure 5: Another view of the work area




Figure 2: Silt fence installed within the creek channel



Figure 4: Another view of the work area Note: the sediment along the sides of the construction project which has been deposited along the edges of the creek



Figure 6: Another view of a portion of the work area



Figure 7: Project area Note: the steep unstabilized slopes



Figure 8: Another view of a portion of the work area



Figure 9: Impacted creek bottom



Figure 1: Tracking on roadway Note: this was a closed roadway



Figure 2: Another view of the extensive sediment on the closed roadway



Figure 3: Tracking on an active roadway




Figure 4: Poorly maintained and installed construction entrance



Figure 5: Another view of tracking on the roadway



Figure 6: Another view of the ineffective construction entrance



Figure 7: Sediment along the road shoulder which is contributing to sediment on the roadway



Figure 8: View of dust on the roadway caused by construction traffic



Figure 9: Rotary broom sweeper.



Figure 10: Another view of the rotary broom sweeper